



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANADate Recovered: 2 MAY 1989Corner Description: NE COR. - NW 1/4 21-23-7Corner Recovered by: A. GUERIN - D. WIMMERMaterial Found: NO STONE FOUND.

- References:
1. 10" IRON POST IN CONCRETE
 2. BOTTLE CAP IN PWR. POLE GR81-12
 3. BOTTLE CAP IN WOOD POST
 4. CONCRETE POST
 5. _____
 6. _____

Condition of Corner: _____

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered of restored the Corner hereon shown and described.

Jorge E. Camacho
 Land Surveyor # 30198

JORGE E. CAMACHO
 REGISTERED
 NO. 30198
 INDIANA
 SURVEYOR

N 1/4 COR. SEC. 21, T23N, R7E

LIBERTY TWP. - GRANT CO.

0041

N 15261.368

E 7974.832

N-11


21

TYPE : GRANT CO. SURVEY MON.

DEPTH : 3"

BY : CO. SURV.

UNCERT'Y :



PROJ. NO. STP3222(026) LINE C

PAGE 82 OF

CENTER SEC. 21, T23N, R7E

LIBERTY TWP. • GRANT CO.

0052

N 12640.964

E 9988.371

2•1

TYPE : 10" DIA. IRON POST FILLED
DEPTH : ABOVE GROUND w/ CONC.

BY :

UNCERT'Y :

