



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANADate Recovered: 2 MAY 1989Corner Description: NE COR - NE $\frac{1}{4}$ 21-23-7Corner Recovered by: A. GUERIN - D. WIMMERMaterial Found: STONE 1.2 COVER

- References:
1. BOTTLE CAP IN PUR. POLE GR81208
 2. FOUNDATION
 3. FOUNDATION
 4. PORCH
 5. _____
 6. _____

Condition of Corner: EXCELLENT


I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.



NE COR. SEC. 21, T23N, R7E
LIBERTY TWP. - GRANT CO.

0042

N 15323.041
E 12669.227



TYPE : RD NAIL IN 3/4" I. PIPE

DEPTH : 1"

BY : CO. SURV.

UNCERT'Y:

